

Report of Thorough Examination of Lifting Equipment to LOLER Regulations

Lifting Operations & Lifting Equipment Regulations 1998 number 2307 regulation 9

CERTIFICATE

Date: 21/08/2020

Report Date: 21/08/2020

Date of examination 19/08/2020

Report Number: Q3361 Container Loading Ramp 02

003

**Name and Address
Of Owner** Forth Ports Grangemouth
Carron House
Dock Road
Grangemouth
FK3 8TY

Site Address / Location Forth Ports Grangemouth

Description of equipment Container Loading Ramp 02
Manufacture Chase Equipment Limited
Date of Manufacture Unknown
Plant No 232157-1
SWL 10 tons

Date of last examination 20/02/2020

Date of next examination 19/02/2021

- a) Identification of any part found to have a defect which is or could become a danger to a persons, stating description of defect, any repair, renewal or alteration required to remedy the defect, either immediately or within a specified time
- b) Identification of other defect(s)
- c) Any other observation(s)

Included will be particulars of any testing / test

Where a defect involves an existing or imminent risk of personal injury a copy will be sent to the local enforcing agency

- a. None
- b. None
- c. The two retaining hooks on the left hand and right hand have no gates. Recommend: Investigate and rectify.
There is moss growing at the bottom of the ramp. Recommend: Remove.
There is general corrosion around the whole ramp. Recommend: Monitor.

I declare that upon the 19 / 08 / 2020 the equipment described in this report was thoroughly examined (unless otherwise stated) in accordance with the lifting operations and lifting Equipment Regulations 1998 SI 2307 and is found safe to use subject to the remedial action to the defects noted upon this report, which are or could become a danger to persons.

Dave Chisholm & Leigh Donnelly



Reviewed by:



Martin Pownall

Port Engineering Services
18 Witney Way
Baldon Business Park
Baldon Colliery
NE35 9PE