

## Report of Thorough Examination to PUWER Regulations

PUWER Regulations 1998

### CERTIFICATE

Date: 10/06/2020

Report Date: 10/06/2020

Date of examination: 08/06/2020

Report Number: Q3216 Shutter Door (Bay 58-002)

---

|                                      |                                                                                   |
|--------------------------------------|-----------------------------------------------------------------------------------|
| <b>Name and Address<br/>Of Owner</b> | DP World London Gateway<br>The Manor way<br>Stanford le Hope<br>Essex<br>SS17 9DP |
|--------------------------------------|-----------------------------------------------------------------------------------|

|                                |                           |
|--------------------------------|---------------------------|
| <b>Site Address / Location</b> | DP World Logistics Centre |
|--------------------------------|---------------------------|

---

**Description of equipment:** Roller Shutter Door

**Manufacture:** Stertil Door

**Date of Manufacture:** 2017

**Plant No:** E292745/3

**SWL:** N/A

**Date of last examination:** 06/07/2018

**Date of next examination:** 08/06/2021

---

- a) Identification of any part found to have a defect which is or could become a danger to a persons, stating description of defect, any repair, renewal or alteration required to remedy the defect, either immediately or within a specified time
- b) Identification of other defect(s)
- c) Any other observation(s)

Included will be particulars of any testing / test

Where a defect involves an existing or imminent risk of personal injury a copy will be sent to the local enforcing agency

- a. None
- b. None
- c. There is severe impact damage to the bottom panel. Recommend: Rectify  
The down button is manual only and the emergency sensor on the bottom of the shutter is unserviceable.  
Recommend: Rectify

**I declare that upon the 08/06/2020 the equipment described in this report was thoroughly examined (unless otherwise stated) in accordance with the lifting operations and lifting Equipment Regulations 1998 SI 2307 and is found safe to use subject to the remedial action to the defects noted upon this report, which are or could become a danger to persons.**

Port Engineering Services  
18 Witney Way  
Baldon Business Park  
Baldon Colliery  
NE35 9PE

**Company:** Port Engineering Services

**Name:** Leigh Donneky  
**Inspection Engineer**

**Signature:**



**Reviewed:** Martin Pownall

**Signature:**

