

Report of Thorough Examination of Lifting Equipment to LOLER Regulations

Lifting Operations & Lifting Equipment Regulations 1998 number 2307 regulation 9

CERTIFICATE

Date: 13/08/2019

Report Date: 13/08/2019

Report Number: Q3361 Fork Truck H7 001

Date of examination 30/07/2019

**Name and Address
Of Owner** Forth Ports Leith
 1 Dock Pl
 Edinburgh
 EH6 7DX

Site Address / Location Forth Ports Leith

Description of equipment Fork Truck H7
Manufacture Hyster
Date of Manufacture 2013
Plant No J019E02014L
SWL 15760kg

Date of last examination First Examination

Date of next examination 30/01/2020

- a) Identification of any part found to have a defect which is or could become a danger to a persons, stating description of defect, any repair, renewal or alteration required to remedy the defect, either immediately or within a specified time
- b) Identification of other defect(s)
- c) Any other observation(s)

Included will be particulars of any testing / test

Where a defect involves an existing or imminent risk of personal injury a copy will be sent to the local enforcing agency

- a. None
- b. Forks close to limit of alignment 3%. Refer to OEM for discard criteria within 1 week.
- c. Fork back plate requires lubrication.

Please Note

Oil level is at 25%

Chains: LH 0.25% RH 0.25%

Forks: Original 90mm LH 86.50 RH 88.00mm

I declare that upon the 30 / 07 / 2019 the equipment described in this report was thoroughly examined (unless otherwise stated) in accordance with the lifting operations and lifting Equipment Regulations 1998 SI 2307 and is found safe to use subject to the remedial action to the defects noted upon this report, which are or could become a danger to persons.



Martin Pownall

Port Engineering Services
18 Witney Way
Boldon Business Park
Boldon Colliery
NE35 9PE