

Report of Thorough Examination of Lifting Equipment to LOLER Regulations

Lifting Operations & Lifting Equipment Regulations 1998 number 2307 regulation 9

CERTIFICATE

Date: 03/05/2019

Report Date: 03/05/2019

Report Number: Q3098 ECH17 Chains 009 1939403

Date of examination 02/05/2019

**Name and Address
Of Owner** DP World Southampton
Western Docks
Southampton
SO15 1DA
United Kingdom

Site Address / Location DP World Southampton

Description of equipment Empty Container Handler
Manufacture Ferrari
Date of Manufacture 2008
Plant No 826356
SWL 9t

Date of last examination 05/03/2019

Date of next examination 02/08/2019

- a) Identification of any part found to have a defect which is or could become a danger to a persons, stating description of defect, any repair, renewal or alteration required to remedy the defect, either immediately or within a specified time
- b) Identification of other defect(s)
- c) Any other observation(s)

Included will be particulars of any testing / test

Where a defect involves an existing or imminent risk of personal injury a copy will be sent to the local enforcing agency

- a. None
- b. Left and right outer chains should both be changed within 4 months, as per previous work order reference: 1898261.
- c. None

Chain inspection.

Outer Left – 0%mm

Outer Right – 0%mm

Inner Left – 0.75%mm

Inner Right – 0.25%mm

I declare that upon the 02 / 05 / 2019 the equipment described in this report was thoroughly examined (unless otherwise stated) in accordance with the lifting operations and lifting Equipment Regulations 1998 SI 2307 and is found safe to use subject to the remedial action to the defects noted upon this report, which are or could become a danger to persons.

George Sizeland



Reviewed by:



Martin Pownall

Port Engineering Services
18 Witney Way
Boldon Business Park
Boldon Colliery
NE359PE