Port Engineering Services
inspection, manufacture and supply

UKAS INSPECTION
4674

Report of Thorough Examination of Lifting Equipment to LOLER Regulations

Lifting Operations & Lifting Equipment Regulations 1998 number 2307 regulation 9

CERTIFICATE

Date: 29/04/2019

Report Date: 29/04/2019

Report Number: Q3098 ECH18 Chains 012 1935778

Date of examination 25/04/2019

Name and Address Of Owner	DP World Southampton Western Docks Southampton SO15 1DA United Kingdom
Site Address / Location	DP World Southampton

Description of equipment	Empty Container Handler
Manufacture	Ferrari
Date of Manufacture	2009
Plant No	426357
SWL	9t
Date of last examination	27/02/2019
Date of next examination	25/07/2019

---

a) **Identification of any part found to have a defect which is or could become a danger to a persons, stating description of defect, any repair, renewal or alteration required to remedy the defect, either immediately or within a specified time**

b) **Identification of other defect(s)**

c) **Any other observation(s)**

Included will be particulars of any testing / test

Where a defect involves an existing or imminent risk of personal injury a copy will be sent to the local enforcing agency

a. None

b. None

c. Both outer chains are close to the discard criteria of 2%. Recommend: Monitor regularly.

Chain inspection.
Right hand side outer chain measured 1.5% wear.
Right hand side inner chain measured 0.5% wear.
Left hand side outer chain measured 1.5% wear.
Left hand side inner chain measured 0.5% wear.

I declare that upon the 25 / 04 / 2019 the equipment described in this report was thoroughly examined (unless otherwise stated) in accordance with the lifting operations and lifting Equipment Regulations 1998 SI 2307 and is found safe to use subject to the remedial action to the defects noted upon this report, which are or could become a danger to persons.

George Sizeland

Reviewed by:

Martin Pownall

Port Engineering Services
18 Witney Way
Boldon Business Park
Boldon Colliery
NE359PE