

Report of Thorough Examination of Lifting Equipment to LOLER Regulations

Lifting Operations & Lifting Equipment Regulations 1998 number 2307 regulation 9

CERTIFICATE

Date: 22/03/2019

Report Date: 22/03/2019

Report Number: Q3098 ECH22 Chains 010 1902240

Date of examination 21/03/2019

**Name and Address
Of Owner** DP World Southampton
Western Docks
Southampton
SO15 1DA
United Kingdom

Site Address / Location DP World Southampton

Description of equipment Empty Container Handler
Manufacture CVS
Date of Manufacture 2009
Plant No ECH22 A26362
SWL 11000kg @ 1200mm @ 5000mm HOL

Date of last examination 21/01/2019

Date of next examination 21/06/2019

- a) Identification of any part found to have a defect which is or could become a danger to a persons, stating description of defect, any repair, renewal or alteration required to remedy the defect, either immediately or within a specified time
 - b) Identification of other defect(s)
 - c) Any other observation(s)
- Included will be particulars of any testing / test
- Where a defect involves an existing or imminent risk of personal injury a copy will be sent to the local enforcing agency

- a. None
- b. Both left and right-hand outer chains are close to the wear limit. Recommend: Changing the outer chains before the next chain inspection. (2 Month)
- c. None

Please Note

Chain inspection only

Left inner – 1.0%mm wear

Left outer – 1.75%mm wear

Right inner – 1.0%mm wear

Right outer – 2.0%mm wear

I declare that upon the 21 / 03 / 2019 the equipment described in this report was thoroughly examined (unless otherwise stated) in accordance with the lifting operations and lifting Equipment Regulations 1998 SI 2307 and is found safe to use subject to the remedial action to the defects noted upon this report, which are or could become a danger to persons.

George Sizeland



Reviewed by:



Martin Pownall

Port Engineering Services
18 Witney Way,
Boldon Business Park,
Boldon Colliery,
NE35 9PE