

Report of Thorough Examination of Lifting Equipment to LOLER Regulations

Lifting Operations & Lifting Equipment Regulations 1998 number 2307 regulation 9

CERTIFICATE

Date: 17/04/2019

Report Date: 17/04/2019

Report Number: Q3098 V141 005 1931273

Date of examination 16/04/2019

Name and Address Of Owner	DP World Southampton Western Docks Southampton SO15 1DA United Kingdom
--------------------------------------	--

Site Address / Location	DP World Southampton
--------------------------------	----------------------

Description of equipment	Straddle Carrier
Manufacture	Kalmar
Date of Manufacture	2016
Plant No	5355
SWL	40t

Date of last examination	17/10/2018
---------------------------------	------------

Date of next examination	16/10/2019
---------------------------------	------------

- a) Identification of any part found to have a defect which is or could become a danger to a persons, stating description of defect, any repair, renewal or alteration required to remedy the defect, either immediately or within a specified time
- b) Identification of other defect(s)
- c) Any other observation(s)

Included will be particulars of any testing / test

Where a defect involves an existing or imminent risk of personal injury a copy will be sent to the local enforcing agency

- a. None
- b. None
- c. The front treads on the left-hand front and rear tyres are worn. Recommend: Rectify
Both right-hand drive gearbox oils are emulsifying. Recommend: Rectify
There are no decals around the mid platform inhibitor switch. Recommend: Rectify
No wash in the window wiper wash bottle. Recommend: Replenish wash bottle
The pantograph support pin has a locking plate missing. Bolts have sheared. Recommend: Rectify

Please note.

Ropes measured at time of inspection using calibrated vernier VPES09GS.

Front left – 21.60mm

Front right – 21.60mm

Rear left – 21.70mm

Rear right – 21.70mm

I declare that upon the 16/04/2018 the equipment described in this report was thoroughly examined (unless otherwise stated) in accordance with the lifting operations and lifting Equipment Regulations 1998 SI 2307 and is found safe to use subject to the remedial action to the defects noted upon this report, which are or could become a danger to persons.

George Sizeland



Reviewed by:



Martin Pownall

Port Engineering Services
18 Witney Way
Boldon Business Park
Boldon Colliery
NE359PE