

Report of Thorough Examination of Lifting Equipment to LOLER Regulations

Lifting Operations & Lifting Equipment Regulations 1998 number 2307 regulation 9

CERTIFICATE

Date: 17/04/2019

Report Date: 17/04/2019

Report Number: Q3098 V142 004 1931276

Date of examination 16/04/2019

**Name and Address
Of Owner** DP World Southampton
Western Docks
Southampton
SO15 1DA
United Kingdom

Site Address / Location DP World Southampton

Description of equipment Straddle Carrier
Manufacture Kalmar
Date of Manufacture 2016
Plant No 5356
SWL 40t

Date of last examination 17/10/2018

Date of next examination 16/10/2019

- a) Identification of any part found to have a defect which is or could become a danger to a persons, stating description of defect, any repair, renewal or alteration required to remedy the defect, either immediately or within a specified time
- b) Identification of other defect(s)
- c) Any other observation(s)

Included will be particulars of any testing / test

Where a defect involves an existing or imminent risk of personal injury a copy will be sent to the local enforcing agency

- a. None
- b. None
- c. The right-hand front tyre tread and side wall worn. Recommend: Rectify
No flashing beacons. Recommend: Rectify
No decals on the right-hand 'E' stop at ground level. Recommend: Rectify
The inhibitor switch on the mid platform has no decals. Recommend: Rectify
2 Window wipers are not working. Recommend: Rectify
No water in window wiper wash bottle. Recommend: Replenish wash bottle
Both the rear sheaves on the spreader support have rope imprint in the grooves. Recommend: Rectify

Rope Measurements

Ropes measured at time of inspection using calibrated vernier VPES09GS.

Front Left - 21.70mm

Front Right – 21.60mm (3 Broken wires. Dry)

Rear Left – 21.90mm

Rear Right – 21.70mm

I declare that upon the 16 / 04 / 2019 the equipment described in this report was thoroughly examined (unless otherwise stated) in accordance with the lifting operations and lifting Equipment Regulations 1998 SI 2307 and is found safe to use subject to the remedial action to the defects noted upon this report, which are or could become a danger to persons.

George Sizeland



Reviewed by:



Martin Pownall

Port Engineering Services
18 Witney Way
Baldon Business Park
Baldon Colliery
NE359PE