Port Engineering Services
inspection, manufacture and supply

UKAS INSPECTION
4674

Report of Thorough Examination of Lifting Equipment to LOLER Regulations

Lifting Operations & Lifting Equipment Regulations 1998 number 2307 regulation 9

CERTIFICATE

Date: 16/05/2019

Report Date: 16/05/2019

Report Number: Q3098 V147 Ropes 004 1951445

Date of examination 15/05/2019

Name and Address Of Owner	DP World Southampton Western Docks Southampton SO15 1DA United Kingdom
Site Address / Location	DP World Southampton

Description of equipment	Straddle Carrier Rope Examination
Manufacture	Kalmar
Date of Manufacture	2016
Plant No	5426
SWL	40t / 50t
Date of last examination	19/11/2018
Date of next examination	15/08/2019

---

a) **Identification of any part found to have a defect which is or could become a danger to a persons, stating description of defect, any repair, renewal or alteration required to remedy the defect, either immediately or within a specified time**

b) **Identification of other defect(s)**

c) **Any other observation(s)**

Included will be particulars of any testing / test

Where a defect involves an existing or imminent risk of personal injury a copy will be sent to the local enforcing agency

a. None
b. None
c. None

Please Note
Exhaust is located near to pipes.
The ropes were found to be of good condition with no deformations or wire breaks.
Ropes measured at time of inspection using calibrated Vernier VPES09GS
Front Left – 21.50mm
Front Right – 21.50mm
Rear Left – 21.80mm
Rear Right – 21.70mm

I declare that upon the 15 / 05 / 2019 the equipment described in this report was thoroughly examined (unless otherwise stated) in accordance with the lifting operations and lifting Equipment Regulations 1998 SI 2307 and is found safe to use subject to the remedial action to the defects noted upon this report, which are or could become a danger to persons.

George Sizeland

Reviewed by:

Martin Pownall

Port Engineering Services
18 Witney Way
Boldon Business Park
Boldon Colliery
NE35 9PE