

Report of Thorough Examination of Lifting Equipment to LOLER Regulations

Lifting Operations & Lifting Equipment Regulations 1998 number 2307 regulation 9

CERTIFICATE

Date: 30/04/2019

Report Date: 30/04/2019

Report Number: Q3098 V64 004 1939332

Date of examination 29/04/2019

Name and Address Of Owner	DP World Southampton Western Docks Southampton SO15 1DA United Kingdom
--------------------------------------	--

Site Address / Location	DP World Southampton
--------------------------------	----------------------

Description of equipment	Straddle Carrier
Manufacture	Noell
Date of Manufacture	2007
Plant No	17080600-01
SWL	40t

Date of last examination	31/10/2018
---------------------------------	------------

Date of next examination	29/10/2019
---------------------------------	------------

- a) Identification of any part found to have a defect which is or could become a danger to a persons, stating description of defect, any repair, renewal or alteration required to remedy the defect, either immediately or within a specified time
- b) Identification of other defect(s)
- c) Any other observation(s)

Included will be particulars of any testing / test

Where a defect involves an existing or imminent risk of personal injury a copy will be sent to the local enforcing agency

- a. None
- b. None
- c. The inhibitor switches have no decals. Recommend: Rectify
The cabinet door on the spreader is held shut with cable ties. Recommend: Rectify
The pantograph rest structure is split. Recommend: Rectify
L2 and L3 steering banana connections have loose bolts and welds cracked. Recommend: Rectify
The rear headlights are not working. Recommend: Rectify
No water in the wash bottle. Recommend: Replenish wash bottle
Both hoist barrels are leaking oil. Recommend: Rectify

Please note

Ropes measured at time of inspection using calibrated vernier VPES09GS.

Front Left – 24.00mm

Front Right – 24.00mm

Rear Left – 24.00mm

Rear Right – 24.00mm

I declare that upon the 29 / 04 / 2019 the equipment described in this report was thoroughly examined (unless otherwise stated) in accordance with the lifting operations and lifting Equipment Regulations 1998 SI 2307 and is found safe to use subject to the remedial action to the defects noted upon this report, which are or could become a danger to persons.

George Sizeland



Reviewed by:



Martin Pownall

Port Engineering Services
18 Witney Way
Boldon Business Park
Boldon Colliery
NE35 9PE