

Report of Thorough Examination of Lifting Equipment to LOLER Regulations

Lifting Operations & Lifting Equipment Regulations 1998 number 2307 regulation 9

CERTIFICATE

Date: 04/06/2019

Report Date: 04/06/2019

Report Number: Q3098 V66 005 1965485

Date of examination 03/06/2019

Name and Address Of Owner	DP World Southampton Western Docks Southampton SO15 1DA United Kingdom
--------------------------------------	--

Site Address / Location	DP World Southampton
--------------------------------	----------------------

Description of equipment	Straddle Carrier
Manufacture	Noell
Date of Manufacture	2007
Plant No	7080600-7
SWL	40t

Date of last examination	11/12/2018
---------------------------------	------------

Date of next examination	03/12/2019
---------------------------------	------------

- a) Identification of any part found to have a defect which is or could become a danger to a persons, stating description of defect, any repair, renewal or alteration required to remedy the defect, either immediately or within a specified time
 - b) Identification of other defect(s)
 - c) Any other observation(s)
- Included will be particulars of any testing / test
- Where a defect involves an existing or imminent risk of personal injury a copy will be sent to the local enforcing agency

- a. None
- b. Cab safety floor panel No 1 is u/s. Rectify within 1 month. Work order reference: 1991804
- c. No ID plate fitted. Recommend: Rectify
Front headlights and drive lights u/s. Recommend: Rectify
Left-hand No 4 wheel steering rod connection is jumping on its threads. Recommend: Rectify
Cab window wash bottle has been removed. Recommend: Rectify
Fire trace is just inside the green. Recommend: Monitor and rectify when necessary
1 x Cab sun visor u/s. Recommend: Rectify

Please Note

Exhaust is located near to pipes.

Ropes measured at time of inspection using calibrated vernier VPES10DC.

Left hand front hoist rope 23.90mm

Left hand rear hoist rope 23.80mm

Right hand front hoist rope 23.50mm

Right hand rear hoist rope 23.80mm

I declare that upon the 03 / 06 / 2019 the equipment described in this report was thoroughly examined (unless otherwise stated) in accordance with the lifting operations and lifting Equipment Regulations 1998 SI 2307 and is found safe to use subject to the remedial action to the defects noted upon this report, which are or could become a danger to persons.

Dave Chisholm



Reviewed by:



Martin Pownall

Port Engineering Services
18 Witney Way
Boldon Business Park
Boldon Colliery
NE359PE