Port Engineering Services
inspection, manufacture and supply

UKAS INSPECTION
4674

Report of Thorough Examination of Lifting Equipment to LOLER Regulations

Lifting Operations & Lifting Equipment Regulations 1998 number 2307 regulation 9

CERTIFICATE

Date: 18/07/2019

Report Date: 18/07/2019
Report Number: Q3098 V82 Ropes 003 1994099

Date of examination 17/07/2019

Name and Address Of Owner	DP World Southampton Western Docks Southampton SO15 1DA United Kingdom
Site Address / Location	DP World Southampton

Description of equipment	Straddle Carrier – Rope Examination
Manufacture	Noell
Date of Manufacture	Unknown
Plant No	V82
SWL	40t/50t
Date of last examination	28/01/2019
Date of next examination	17/10/2019

---

a) **Identification of any part found to have a defect which is or could become a danger to a persons, stating description of defect, any repair, renewal or alteration required to remedy the defect, either immediately or within a specified time**
b) **Identification of other defect(s)**
c) **Any other observation(s)**

Included will be particulars of any testing / test

Where a defect involves an existing or imminent risk of personal injury a copy will be sent to the local enforcing agency

a. None

b. None

c. None

Rope examination only
Please Note
Ropes measured at time of inspection using calibrated Vernier VPES10DC
Front Left – 23.90mm
Front Right – 23.90mm
Rear Left – 24.00mm
Rear Right – 24.00mm

I declare that upon the 17 / 07 / 2019 the equipment described in this report was thoroughly examined (unless otherwise stated) in accordance with the lifting operations and lifting Equipment Regulations 1998 SI 2307 and is found safe to use subject to the remedial action to the defects noted upon this report, which are or could become a danger to persons.

Dave Chisholm / Paul Funderburk

Reviewed by:

Martin Pownall

Port Engineering Services
18 Witney Way
Boldon Business Park
Boldon Colliery
NE35 9PE