

Report of Thorough Examination of Lifting Equipment to LOLER Regulations

Lifting Operations & Lifting Equipment Regulations 1998 number 2307 regulation 9

CERTIFICATE

Date: 21/03/2019

Report Date: 21/03/2019

Report Number: Q3098 V83 004 1912704

Date of examination 20/03/2019

**Name and Address
Of Owner** DP World Southampton
Western Docks
Southampton
SO15 1DA
United Kingdom

Site Address / Location DP World Southampton

Description of equipment Straddle Carrier
Manufacture Noell
Date of Manufacture 2006
Plant No 15000671 V83
SWL 40t

Date of last examination 20/09/2018

Date of next examination 20/09/2019

- a) Identification of any part found to have a defect which is or could become a danger to a persons, stating description of defect, any repair, renewal or alteration required to remedy the defect, either immediately or within a specified time
- b) Identification of other defect(s)
- c) Any other observation(s)

Included will be particulars of any testing / test

Where a defect involves an existing or imminent risk of personal injury a copy will be sent to the local enforcing agency

- a. None
- b. None
- c. The rear spreader locating pin welded bracket is cracking round the old weld repair. Recommend: Rectify
The front side shift slide bracket has loose bolts. Recommend: Rectify
All four bumpers are dented. Recommend: Rectify
The right-hand rear LED light is not working. Recommend: Investigate and rectify
The right-hand front twist lock cylinder is leaking oil from the fitting. Recommend: Rectify
2 Window wiper switches are broken. Recommend: Rectify
The front window wiper water feed pipe is not connected. Recommend: Rectify
There is no water in the wash bottle. Recommend: Replenish wash bottle
The "E" stop on the top platform has no decals round it. Recommend: Rectify

Please Note

The ropes were found to be of good condition with no deformations or wire breaks.

Ropes measured at time of inspection using calibrated Vernier VPES09GS.

Front Left – 23.50mm

Front Right – 23.60mm

Rear Left – 23.60mm

Rear Right – 23.70mm

I declare that upon the 20 / 03 / 2019 the equipment described in this report was thoroughly examined (unless otherwise stated) in accordance with the lifting operations and lifting Equipment Regulations 1998 SI 2307 and is found safe to use subject to the remedial action to the defects noted upon this report, which are or could become a danger to persons.

George Sizeland



Reviewed by:



Martin Pownall
Port Engineering Services
18 Witney Way
Boldon Business Park
Boldon Colliery
NE35 9PE