Port Engineering Services
inspection, manufacture and supply

UKAS INSPECTION
4674

Report of Thorough Examination of Lifting Equipment to LOLER Regulations

Lifting Operations & Lifting Equipment Regulations 1998 number 2307 regulation 9

CERTIFICATE

Date: 13/09/2019

Report Date: 13/09/2019
Report Number: Q3098 V84 005 2029498

Date of examination 10/09/2019

Name and Address Of Owner	DP World Southampton Western Docks Southampton SO15 1DA United Kingdom
Site Address / Location	DP World Southampton

Description of equipment	Straddle Carrier
Manufacture	Noell
Date of Manufacture	2006
Plant No	15000672
SWL	40t
Date of last examination	06/03/2019
Date of next examination	10/03/2020

---

a) **Identification of any part found to have a defect which is or could become a danger to a persons, stating description of defect, any repair, renewal or alteration required to remedy the defect, either immediately or within a specified time**
b) **Identification of other defect(s)**
c) **Any other observation(s)**

Included will be particulars of any testing / test

Where a defect involves an existing or imminent risk of personal injury a copy will be sent to the local enforcing agency

a. None
b. Hoist barrel oil levels are depleted. Rectify within 1 month. Work order reference: 2064964
c. 3 x Bumpers minor impact damage. Recommend: Monitor and rectify when necessary
Left hand front spreader station lock 1 x weld u/s. Recommend: Rectify
1 x Cab sun visor u/s. Recommend: Rectify
Cab window wash bottle is depleted. Recommend: Replenish wash bottle.
3 x Top work lights u/s. Recommend: Investigate and rectify
2 x Bumpers the top flanges are bent and split. Recommend: Rectify
Left hand no 2 tyre wall is split. Recommend: Monitor and rectify when necessary.

Please Note
Exhaust is located near pipes
The ropes were found to be of good condition with no deformations or wire breaks.
Ropes measured at time of inspection using calibrated Vernier VPES10DC
Front Left – 23.80mm
Front Right – 23.70mm
Rear Left – 23.80mm
Rear Right – 23.80mm

I declare that upon the 10 / 09 / 2019 the equipment described in this report was thoroughly examined (unless otherwise stated) in accordance with the lifting operations and lifting Equipment Regulations 1998 SI 2307 and is found safe to use subject to the remedial action to the defects noted upon this report, which are or could become a danger to persons.

Dave Chisholm / George Sizeland

Reviewed by:

Martin Pownall
Port Engineering Services
18 Witney Way
Boldon Business Park
Boldon Colliery
NE35 9PE